

```
=====
SMG2-installation procedure for rework  V1.01          BMW TI-430 Gall
=====
SMG2-installation procedure
=====
vehicle with VIN :  not readable
=====
start diagnostics
  read engine speed :    0
=====
adapt longitudinal acceleration sensor
  test status : Testprogramm beendet
  info status : Kein Fehler
=====
adapt clutch valve
  test status : Testprogramm nicht ordnungsgemaess beendet
  info status : Einkuppelposition ausserhalb der zulaessigen Toleranz
=====
break at:  adapt clutch valve
=====
```