Whole vehicle inspection report	
Time: 2024-07-08 22:22:04	
Vehicle name: M3 VIN: WBSBL93471JR10378	
11 5 9)
Number of Number of normal failed of failure systems	
ECM Engine Control Module	0
EWS Elec. Immobilize System	1
oF power on reset	>
ABS/ACS/DSC Dynamic	3
Stability Control	
Yessure sensors	>
93 CAN data fault from DME/DDE	>
<u></u> 86	>
Timeout, instrument cluster	
LEW Steering-angle Sensor	0
MFL Multi-function Steering Wheel	0
MRS Multiple	
Restraint System	1
17 Sonsor for side airbag, right	>
Sensor for side airbag, right	
IKE/IKI/KOMBI Instrument Cluster	0
LSZ/LCM Light Switching Center	0
	4
IHKA/IHKR AC/Heater	
Solar sensor or Latent heat storage system Temperature sensor	
RLS Rain/Light Sensor	0
ZKE Central Body Electronic	0
SMF Seat Memory, Driver	0
RAD Radio	0
SHD Sliding/tilting Sunroof	0
SPMFT Mirror memory,driver	0
SZM Switching Center, Center Console	3
	>
1 3D020206	
The fault code is not found in the database, Please contact us to confirm.	
02 Seat heating, left, short or open circuit	>